

Spare Parts for MILWAUKEE M18FHIWF12-502X

HIGH TORQUE



Part code	Description	QT
4931465519	Feed Screw	4
4931465310	Gear Box	1
4931465311	Axial bear. washer	1
4931416493	Circlip	1
4931416492	O-Ring	1
4931436148	Ball	3
4931465312	Hammer	1
4931440453	Ball	28
4931465313	Bearing washer	1
4931465314	Spring	1
4931465316	Planetary drive	3
4931465318	Gasket	1
4931465319	Holding ring	1
4931465322	Ball bearing	1
4931465323	Bearing cover	1
4931465324	Screw	5

4931465325	Screw	2
4931465326	Screw	4
4931465328	Switch lever	1
4931465329	Switch	1
4931465330	Rotor	1
4931465332	Driving shaft	1
4931465333	Electronic switch	1
4931465334	Housing	1
4931436160	Clamp	1
4931465335	Carrying case	1
4931465336	Insert	1